

## **Product Safety Report**

Dongguan Xike Silicone Technology Dummy Clip	
Aspect	Details
Images	SHEIN Q () () () () () () () () () () () () ()
PSD Number	2509-0064
Product Type	Childcare articles and children's equipment - Pacifiers/Teething Rings
Product Identifiers	Brand: Shein, Dongguan Xike Silicone Technology Model: XK-LZ-00007 Barcode: 2507211355078 Listing name: 1-Pack Baby Pacifier Anti-Lost Chain with Clip Batch: 08/10/2024
Product Description	Green silicone dummy clip in the form of a caterpillar.
Country of Origin	China
Counterfeit	Unknown
Risk Level	Serious
Risk Type	Strangulation
Risk Description	The dummy clip presents a serious risk of injury as it exceeds the maximum permitted length and does not meet the minimum required thickness for such products. If the cord becomes wrapped around a child's neck, especially when unsupervised, it could lead to strangulation or choking. The reduced diameter increases the likelihood of the cord breaking, creating additional choking hazards from small parts.  The product does not meet the requirements of the General Product Safety
Corrective Measures	Regulations 2005.  Consumers are advised to stop using the product immediately and keep it out of the reach of young children.  Contact the distributor you purchased from to request redress.
Online	Shein – The listing has been removed by the online marketplace.
1	Local Authority Trading Standards

The OPSS Product Safety Alerts, Reports and Recalls Site can be accessed at the following link: <a href="https://www.gov.uk/guidance/product-recalls-and-alerts">https://www.gov.uk/guidance/product-recalls-and-alerts</a>