

Air Quality and Dust Monitoring Monthly Report – June 2026

London Borough of Hammersmith and Fulham



Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,
Two Snowhill
Snow Hill Queensway
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2026, except where otherwise stated. Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v3.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-government-licence/version/3 **OGL** or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.



Monthly Summary

- 1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Hammersmith and Fulham (LBHF) during May 2026 and June 2026 respectively.
- 1.1.2 Figure 1 and Figure 2 in Appendix A present the current worksites together with air quality and dust monitoring locations.
- 1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.
- 1.1.4 The current worksites, as presented in Appendix A, Figure 1 and Figure 2, include:


Old Oak Common Depot

- General Site: General site-wide housekeeping and general site tidying, plant and traffic set-up and movement, relocating and reinstating site fences, housekeeping and tidying, traffic management for site-wide access.
- Station Box: Steel fixing, general carpentry, concrete works, and compaction, scaffolding, and mastic installation.
- GWML and SAB: Blockwork in the SAB and west core, demobilisation from SAB, muck away and backfill operations, steel fixing, general carpentry.
- Site Haul Roads and Public Roads Adjacent to Site: Clean the site haul roads with a road sweeper, clean the public roads on Old Oak Common Lane and Wells House Road with a road sweeper, clean the public pavements on Wells House Road and Old Oak Common Lane, clean the areas around OOH and the Welfare Compound with a ride-on scrubber dryer, clean vehicle wheels with a wheel wash and two jet wash units, dust suppression on the site haul roads and footpaths with a water bowser.
- OOCL: Digging for SSEN ducts and excavations for service transfer, dig for SSEN in North UTX and backfill SSEN in South UTX, excavate for service connections, dig for distribution and cut and cap the main, dig for comms, removal of tanks and tidy up, muck away and backfill operations, excavation works, excavating for crane mat and grading crane base, pile bursting, over-pumping pipework and groundworks (west side), plant and traffic movement.
- MEPH: Installing modules on Platform 10, moving equipment, tools and materials to Platform 10, moving VCBs.
- Blockwork: building blockwork (SAB and west core), ongoing block wall construction, blockwork in SAB rooms.
- Attenuation Tank: Material moving, loading and unloading in AD03 and Ado9.

- 1.1.5 Four (4) dust monitors are installed around these worksites, where works are underway. These sites returned a medium to high dust risk rating.
- 1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor presented in Figure 3. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.
- 1.1.7 The trigger level for PM₁₀ concentrations of 190 µg/m³, over a 1-hour period, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – (October 2018)*' has been applied.
- 1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (June 2026).
- 1.1.9 Diffusion tube monitoring of Nitrogen Dioxide (NO₂) is undertaken at seven (7) locations around highways within the LBHF as part of the management of air quality where significant effects may occur as a result of the scheme.
- 1.1.10 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.
- 1.1.11 NO₂ monitoring locations and results are presented in Appendix C, Table 2, together with the 2026 running mean.
- 1.1.12 There were no (0) complaints received during the reporting period (June 2026).

Appendix A – Worksites and Monitoring Locations

Figure 1 and 2: Worksites and monitoring locations within the LBHF



Legend

● Dust Monitor Worksite

■ Diffusion Tube District Borough Unitary Boundaries

Service Layer Credits: GB Topographic: Contains OS data © Crown Copyright and database right 2025
Contains data from OS Zoomstack

Map Number
Map Name
Worksite and Monitoring Locations In LBHF (Sheet 1)
London Borough of Hammersmith and Fulham



HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.


Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway,
Birmingham B4 6GA.

© Crown copyright and database rights 2025.
Ordnance Survey Licence Number 100049190.

Doc Number:




Scale at A3: 1:10,000



Metres

Date: 06/02/25



Legend

- Diffusion Tube
- District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

**Monitoring Locations In LBHF
(Sheet 2)**

**London Borough of Hammersmith
and Fulham**

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway,
Birmingham B4 6GA.

Scale at A3: 1:10,000

0 100 200 300 400
Metres


Doc Number: **Date: 08/12/20**

Appendix B – Dust Monitoring Results

Table 1: Dust Monitoring Locations and Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM ₁₀ concentration (µg/m ³)	Minimum 1-hour PM ₁₀ concentration (µg/m ³)	Maximum 1-hour PM ₁₀ concentration (µg/m ³)	Number of 1-hour periods exceeding trigger level of 190 µg/m ³	Data capture (%)
AQ028	521302, 182067	Wells House Road	M	Yes	No	17.7	1.9	109.5	0	100.0
AQ029	521453, 182132	Old Oak Common	H	Yes	No	10.6	1.6	57.1	0	93.3
AQ035	521353, 181959	Old Oak Common	H	Yes	No	15.8	1.5	103.6	0	100.0
AQ036	521482, 181668	UTX South – Triangle Site	M	Yes	No	13.9	2.1	45.1	0	100.0

Figure 3: Construction dust 1-hour mean indicative PM₁₀ concentration for all dust monitors



Appendix C – Air Quality Monitoring Results

Table 2: NO₂ monitoring locations around highways NO₂ concentrations and monthly monitoring results with running mean for 2026 (µg/m³)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean ¹²
HS2-000020BN2	Lamp post on Du Cane Road	523092, 181264	Tube Missing	35	35	Tube Missing	30								33
HS2-000020BN4	End of cycle lane sign on Old Oak Road	521625, 180871	36	32	37	33	30								34
HS2-000020BNR	Lamp posts in Shepherd's Bush Common	523481, 179871	36	28	26	27	22								28
HS2-000020BPP	Sign post on A219 Scrubs Lane, South of Harrow Road	522378, 182877	40	32	31	26	28								31
HS2-000020BPT	Controlled Zone/Zone Ends road sign on A219 Scrubs Lane, north of Hythe Road	522478, 182517	40	27	32	27	19								29
HS2-000020BQE	Lamp post next to No 11 Wulfstan Street	521996, 181118	29	25	23	19	18								22
HS2-000020BQW	Lamp post on A402 Goldhawk Road	522037, 179209	30	27	28	23	18								25

¹ Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.

² The annual mean for diffusion tubes presented in the table above still require various analysis and adjustments to be undertaken before comparison to the Air Quality Objectives. The final corrected annual mean will be presented in the HS2 Annual Air Quality Report.