HS2

July 2026

Air Quality and Dust Monitoring Monthly Report – July 2026

City of Westminster

© HS2 Ltd.

gov.uk/hs2

Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,
Two Snowhill
Snow Hill Queensway
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2026, except where otherwise stated. Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v3.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/3 OGL or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.

recycle

Monthly Summary

1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality monitoring undertaken in the City of Westminster (CoW) during June 2026.

1.1.2 Figure 1 and Figure 2 in Appendix A present the current air quality monitoring locations.

1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.

1.1.4 There are no current worksites located within the CoW. Therefore, no dust monitoring has been carried out.

1.1.5 Diffusion tube monitoring of Nitrogen Dioxide (NO_2) was undertaken at thirteen (13) locations around highways within the CoW as part of the management of air quality where significant effects may occur as a result of the scheme.

1.1.6 Diffusion tube monitoring results are provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.

1.1.7 NO_2 monitoring locations and results are presented in Appendix B, Table 1, together with the 2026 running mean.

1.1.8 There were no (0) complaints received during this reporting period (July 2026).

Appendix A –Monitoring Locations

Figures 1 and 2: Current monitoring locations within the CoW



Legend

- Diffusion Tube
- District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Monitoring Locations In CoW (Sheet 1)

City of Westminster

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

Scale at A3: 1:10,000

0 100 200 300 400
Metres

© Crown copyright and database rights 2021. Ordnance Survey Licence Number 100049190.

Doc Number:

Date: 03/03/21



Legend

- Diffusion Tube
- District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Monitoring Locations In CoW (Sheet 2)

City of Westminster

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

Scale at A3: 1:10,000

0 100 200 300 400
Metres

© Crown copyright and database rights 2020. Ordnance Survey Licence Number 100049190.

Doc Number:

Date: 08/12/20

Appendix B – Air Quality Monitoring Results

Table 1: NO_2 monitoring locations around highways, NO_2 concentrations and monthly monitoring results with running mean for 2026 (µg/m^3)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[1] [2]
HS2-000020BMD	Lamp post on Park Crescent Road	528776, 182170	24	Tube Missing	36	36	22	45							33
HS2-000020BME	Lamp post in between A501 and A4201	528901, 182180	40	51	40	44	42	54							45
HS2-000020BMX	Sign post by roundabout on A5205	527206, 182887	37	36	28	23	26	38							31
HS2-000020BMY	Lamp post between Blomfield Road and Edgware Road	526549, 182226	Tube Missing	35	32	24	29	36							31
HS2-000020BND	Outer Circle Regent's Park	528276, 182185	29	30	23	19	16	20							23

[1] Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.
[2] The annual mean for diffusion tubes presented in the table above still require various analysis and adjustments to be undertaken before comparison to the Air Quality Objectives. The final corrected annual mean will be presented in the HS2 Annual Air Quality Report.

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[1 2]
HS2-000020BNJ	Light post on Park Road	527359, 182633	42	36	33	29	30	47							36
HS2-000020BNL	Lamp post on Penfold Street	526914, 182077	33	26	25	19	19	27							25
HS2-000020BP1	Lamp post on Brook Street	528597, 180942	Tube Missing	37	32	27	26	38							32
HS2-000020BPG	Lamp post on St John's Wood Street	527019, 182748	32	30	25	20	21	29							26
HS2-000020BPH	Lamp post St John's Wood Terrace	526818, 183164	36	33	28	21	21	Tube Missing							28
HS2-000020BQU	Lamppost outside Edgware Road Station	527048, 181731	39	Tube Missing	Tube Missing	37	33	51							40
HS2-000020BQY	Sign post on Ladbroke Grove	523867, 182466	49	33	36	34	31	25							35
HS2-000020BP3	Triplicate site next to the Marylebone Road kerbside automatic monitoring stations	528125, 182016	43	40	39	33	37	55							41