HS2

August 2026

Air Quality and Dust Monitoring Monthly Report – August 2026

Buckinghamshire Council

© HS2 Ltd.

gov.uk/hs2

Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,
Two Snowhill
Snow Hill Queensway
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2026, except where otherwise stated.

Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v3.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-governmentlicence/ version/3 OGL or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.

recycle

Monthly Summary

1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High-Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of dust monitoring undertaken in the Buckinghamshire Council (BC) during August 2026.

1.1.2 Figures 1-6 in Appendix A present the current worksites together with the dust monitoring locations.

1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.

1.1.4 The current worksites, as presented in Appendix A, Figures 1-6, include:

CVV LTP1

- North Embankment Compound: Compound operation;
- DWSC Compound: Compound operation;
- Haul Road: Haul road maintenance;
- ATFS: Permanent drainage, soiling and seeding, ATFS access road construction and slab removal;
- Pumping Water Management;
- Satellite Welfares;
- South Abutment: Drainage works, South Abutment construction stage 2 – earthworks, yard supporting activities, soiling and seeding works, launching girder platform removal;
- Environmental Maintenance;
- Stockpiling Activity HOAC: Stockpile management;
- Deck Finishes Logistics: Preparation and operation of storage yards and installation of below deck access provision, traffic management on the deck surface, delivery of parapets, noise barriers, troughs, pipes, steel works and other minor materials to the storage yards and deck, installation of access at the top of the deck (HAKI stairs) and finishes support plan;
- Deck Finishes – On-deck Construction: North abutment works, deck waterproofing, SFRC slab construction, north embankment and south embankment noise barriers and foundations, noise barrier and concrete panel installation at north embankment and masking wall installation at north embankment and south embankment;
- Deck Finishes – In-deck Construction: Structural health monitoring;
- Landscaping: Advanced works including removal of cofferdam, initial ground drainage including manhole chamber, landscaping, hardstanding removal and tree removal & vegetation clearance and street works – bellmouth road construction; and
- General site activities.

Chalfont St Peter Vent Shaft

- General Site Activities;
- Road Maintenance Works;
- Ground Level Works (External Works Part 2);
- Building Trades: brickworks and internals; and
- Demobilisation.

Amersham Vent Shaft

- General Site Activities; and
- Land Drainage Works.

Chalfont St Giles Vent Shaft

- General Site Activities; and
- Demobilisation.

Little Missenden Vent Shaft

- General Site Activities

Chesham Intervention Shaft

- General site activity; and
- Landscaping.

North Portal

- General Plant: Site Activities;
- Tracks Platform;
- Piling Platform Reinstatement;
- Porous Portal Structure;
- North Portal Building;
- Tunnel Support: Batching Plant operation and concrete distribution and tunnel walkway slip forming; and
- Tracks Drainage and Utilities.

South Heath

- South Heath Earthworks & Drainage: Cutting and landscaping;
- General Earthworks: Site operations & support vehicles, stockpile management, surface water management, compounds and general maintenance;
- South Heath drainage: Earthworks for track drainage, stockpile and landscaping bunds drainage and collection chamber construction;
- Utilities: Excavation and construction, installation of utilities and connection of new utilities;
- Great Missenden Compound: Plant and compound maintenance, utilities work and site security at Great Missenden roundabout;
- GMI/2 Overbridge: Site security, construction of FRC structure, deck finishes and cutting finishes;
- GMI/12 Overbridge: Site security, excavation & pile cropping, construction of FRC structure, deck finishes and cutting finishes;

- Ground Investigation Works: Borehole drilling, geo-physical investigations, ground investigation and mitigation;
- Site Access Road and Mass Haul Route construction and maintenance: lime spreading, tarmac & concrete surfacing; and
- Road Utilisation: SAR utilisation and MHR utilisation.

North Chilterns to Aylesbury Area

BLOB

- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)
- Earthworks

TLE/2

- Pier cladding
- Earthworks
- Pile shell construction
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)

Bowood Lane Land Drainage

- Sheeted pits completed
- Auger boring ongoing

Wendover Dean Viaduvt

- Deck pours
- Robust kerb pours
- Earthworks
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)

Rocky Lane Underbridge

- Parapet installation
- Concrete stitch pours
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)

Small Dean Lane

- Removal of the conveyor sections
- Earthworks
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)

Grove Farm Culvert

- Second TBM drive from shaft 2 to shaft 3
- Box culvert blinding

Wendover Green Tunnel

- Earthworks
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)
- Installation of pre-cast concrete segments to the tunnel
- Backfill
- Concrete pours
- Waterproofing

Self-Propelled Modular Transporter (SPMT)
- Segment installation

ELL/20
- Ongoing construction of east and west embankment

Wendover North Cutting Excavation
- Dewatering
- Excavating

Nash Lee Ditch Slabs
- Concrete pours
- Excavation
- Overpumping

Nash Lee Overbridge
- Deck pours
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)

Stoke Mandeville South Embankment
- Noise Barrier Piling
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)
- Stockpile maintenance and management

Oxford Road Embankment
- Earthworks including excavation, backfilling and embankment construction
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)

SMA/16 Overbridge
- Abutment backfill
- Embankment stabilisation works

SBH19 Overbridge
- Bearing installation
- Connect bridge to bearings and grout

Aylesbury Embankment
- Earthworks including excavation, backfilling and embankment construction
- Landscape area
- Use and maintenance of Mass Haul Road (MHR) and Site Access Road (SAR)

Aylesbury South Cutting
- Earthworks including backfilling

TVV South and North Embankment
- Earthworks including soil profiling, structural backfill and embankment construction

TVV
- River Thame scour protection works
- Platform removal
- Concrete protection slab

- Waterproofing

Putlowes Drive
- Archaeology works

FMA/1
- Night closure works
- Tie-in works to the PRoW

Bicester Road Embankment
- Earthworks including excavate and replace

WAD4 Overbridge
- Deck reinforcement
- Concrete deck pour

WAD3 Underpass
- Waterproofing
- Track drainage
- Land drainage
- Earthworks

Waddesdon North Cutting
- Earthworks including backfilling

Quainton South Embankment
- Earthworks including structural backfill, embankment construction and landscape bund fill

North Chilterns to Aylesbury Area

Turweston West
- Noise Barrier Piling at Turweston Embankment & Cutting
- Water management / pumping activities
- Use and maintenance of Mass Haul Road and Site Access Road

Turweston East
- Screening of material
- Use and maintenance of Mass Haul Road and Site Access Road

Turweston North
- Rock buttress cut and fill.
- Landscaping on Turweston Green Overbridge

School End
- School End GSMR Platform excavation.
- Chetwode Cutting North: Bulk Excavation
- Use and maintenance of MHR and SAR.
- Compound Maintenance.
- Devegetation including strimming and failing.
- Water management / pumping activities.
- Stockpiling/ Topsoil Screening

- Use and maintenance of Mass Haul Road and Site Access Road

Hermitage
- Noise Barrier breaking, cropping, steel fixing, blinding, and concreting pile caps
- Chetwode Cutting Central:- Bulk Excavation
- Use and maintenance of MHR and SAR.
- Water management / pumping activities.

Twyford
- PBI-5A Overbridge- striking formwork, parapet deliveries, concrete repair works.
- Twyford Embankment- Shear Key excavation, stabilization works, Core Bund installation
- Twyford Viaduct- Parapet Deliveries and Installation, concrete stich pours
- Track Drainage installation
- Use and maintenance of MHR and SAR.
- Water management / pumping activities.
- Devegetation
- Excavation of ditch under Twyford Maintenance Access Slab

Calvert (FCC and School Hill Monitor)
- School Hill batching plant – production of concrete.
- School Hill Overbridge – FRC works.
- School Hill Road Realignment – VacEx for utilities
- Calvert Green overbridge – FRC works.
- Aggregate deliveries along the site access road (SAR).
- Calvert Cutting earthworks – drainage and general maintenance activities.
- CBGM batching plant – production of CBGM

Woodlands
- Woodlands Cutting – Dig & Replace.
- Woodland Drop Inlet Culvert works.
- Adamas Accommodation – Technical backfill and back of wall drainage.
- Aggregate deliveries along the SAR.

Quainton
- Earthworks - Ongoing
- Utility diversions.
- Station Road Realignment (East tie-in) – de-vegetation, old tarmac removal.

Other works ongoing, where no dust monitoring is being undertaken include:
- Turweston Viaduct
- A422 Overbridge
- Grovehill Embankment
- Westbury Viaduct
- Various Slab Crossings
- West Street overbridge
- Portway culvert
- Perry Hill overbridge
- EWR culvert
- IMD West culvert

- IMD East Culvert
- Shepherds Furze earthworks (stockpile maintenance)
- Shepherds Furze culvert
- MCJ4 chord earthworks
- Infrastructure maintenance depot (IMD) earthworks
- Secant retaining wall
- Bat mitigation structure
- SCL/13 overbridge
- FCC Cell 6 earthworks (stockpile maintenance)
- FCC Access Road Retaining Wall
- Sheephouse Wood North culvert
- Greatmoor no. 4 culvert and CAG2 underbridge
- Megaditch retaining wall
- Greatmoor no. 3 culvert
- GUN28 overbridge
- QUA36 overbridge
- Hills farm earthworks (stockpile maintenance)
- Edgcott Road overbridge
- QUA26 Underbridge
- Doddershall Embankment earthworks
- Doddershall No. 6 and No. 7 Culvert
- Quainton cutting
- QUA28 overbridge
- Station Road overbridge
- Station Road Network Rail overbridge

1.1.5 Twenty-nine (29) dust monitors are installed around these worksites, where works are underway. These sites returned a medium dust risk rating.

1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor presented in Figure 7. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.

1.1.7 The trigger level for PM_{10} concentrations of 190 µg/m^3, measured as a 1-hour mean, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – (December 2018)*' has been applied.

1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (August 2026).

1.1.9 Data capture was below 90% at multiple dust monitors during August 2026. Reduced data capture was associated with the decommissioning of the Chesham Lane monitor on 19th August 2026, installation of new monitors at Golf Course East Ditch on 27th August 2026

and Turweston West on 20th August 2026, and relocation of the Turweston East monitor on 20th August 2026. Additional losses occurred at CHStP-AQMP1b due to an ongoing controller fault, despite replacement components being fitted on 11th August 2026; LMS-AQMP2 due to a server issue resolved on 4th August 2026; and ORC-AQMP1 due to a network fault, with replacement parts ordered for installation in early September 2026. Align has also yet to relocate and provide power to CHStP-AQMP1a.


1.1.10 Table 1 provides a summary of the complaint information relating to dust or air quality received during the reporting period, together with the findings of any related investigations.

Table 1: Summary of complaints received during August 2026

Complaint Reference No.	Worksite Reference	Description of complaint	Results of investigation
HS2-26-47638-C	N/A	Increased amount of dust in the area, covering personal property.	Resident has been assured that during the current dry spell that dust suppression is a priority, and our Environmental and Delivery Teams are working together to ensure mitigation measures are in place and monitoring systems are fully operational. No Exceedances have been recorded.
HS2-26-47648-C	N/A	Dust everywhere and filthy cars.	Resident has been assured that during the current dry spell that dust suppression is a priority, and our Environmental and Delivery Teams are working together to ensure mitigation measures are in place and monitoring systems are fully operational. No Exceedances have been recorded.

Appendix A – Worksite and Dust Monitoring Locations

Figures 1-6: Worksite and Monitoring locations within BC



Legend

- Dust Monitor
- District Borough Unitary Boundaries

Service Layer Credits: GB Topographic: Contains OS data © Crown Copyright and database right 2025
Contains data from OS Zoomstack

Map Number

Map Name

Monitoring Locations In BC (Sheet 1)

Buckinghamshire County

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.


© Crown copyright and database rights 2025.
Ordnance Survey Licence Number 100049190.

Scale at A3: 1:40,000

0 0 0 0 0 0 0
Metres

Doc Number:

Date: 10/07/25



Legend

- Dust monitor
- District Borough Unitary Boundaries
- Worksite

Service Layer Credits: GB Topographic: Contains OS data © Crown Copyright and database right 2025
Contains data from OS Zoomstack

Map Number

Map Name

Worksite & Monitoring Locations In BC (Sheet 2)

Buckinghamshire County

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2025. Ordnance Survey Licence Number 100049190.


Scale at A3: 1:32,000

0 330 660 990 1,320

Metres

Doc Number:

Date: 10/07/25



Legend

- Dust Monitor
- District Borough Unitary Boundaries

Service Layer Credits: GB Topographic: Contains OS data © Crown Copyright and database right 2026.
Contains data from OS Zoomstack

Map Number

Map Name

Monitoring Locations In BC (Sheet 3)

Buckinghamshire County

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2026.
Ordnance Survey Licence Number 100049190.


Scale at A3: 1:10,000

0 100 200 300 400

Metres

Doc Number:

Date: 28/04/26



Legend

- Dust Monitor
- District Borough Unitary Boundaries

Service Layer Credits: GB Topographic: Contains OS data © Crown Copyright and database right 2026.
Contains data from OS Zoomstack

Map Number

Map Name

Monitoring Locations In BC (Sheet 4)

Buckinghamshire County

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2026.
Ordnance Survey Licence Number 100049190.


Scale at A3: 1:12,000

0 120 240 360 480

Metres

Doc Number:

Date: 28/04/26



Legend

Dust Monitor
District Borough Unitary Boundaries
Worksite

Service Layer Credits: GB Topographic: Contains OS data © Crown Copyright and database right 2026.
Contains data from OS Zoomstack

Map Number

Map Name

Worksite and Monitoring Locations In BC (Sheet 5)

Buckinghamshire County

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2026.
Ordnance Survey Licence Number 100049190.


Scale at A3: 1:6,000

0 60 120 180 240

Metres

Doc Number:

Date: 28/04/26



Legend

- Dust Monitor
- District Borough Unitary Boundaries
- Worksite

Service Layer Credits: GB Topographic: Contains OS data © Crown Copyright and database right 2025
Contains data from OS Zoomstack

Map Number

Map Name

Worksite and Monitoring Locations In BC (Sheet 6)

Buckinghamshire County

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2025. Ordnance Survey Licence Number 100049190.

Scale at A3: 1:12,000

0 120 240 360 480

Metres

Doc Number:

Date: 10/07/25

Appendix B – Dust Monitoring Results


Table 1: Dust Monitoring Locations and Results


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM_{10} concentration ($\mu g/m^3$)	Minimum 1-hour PM_{10} concentration ($\mu g/m^3$)	Maximum 1-hour PM_{10} concentration ($\mu g/m^3$)	Number of 1-hour periods exceeding trigger level of 190 $\mu g/m^3$	Data capture (%)
CHStP-AQMP1b	500093, 192996	Relocated from CHStP-NMP1 to site-boundary outside residence	M	Yes	Yes	5.6	1.0	33.0	0	66.3
CHStP-AQMP2	499951, 193282	On the western boundary of the site	M	Yes	Yes	2.5	0.1	40.4	0	98.1
CHStP-AQMP3	499781, 192747	Near Haul Road Access at Southern End of Site	M	Yes	Yes	9.7	6.6	31.4	0	99.7
CHStG-AQMP1	497170, 194752	On the southern boundary close to Hobbs Hole Cottage	M	Yes	Yes	5.2	1.0	37.0	0	98.7
CHStG-AQMP2	497320, 194770	On southern boundary next to carpark	M	Yes	Yes	4.9	1.0	28.0	0	99.3
LMS-AQMP1	493190, 198848	On the south-west of the site	M	Yes	Yes	4.0	1.0	24.0	0	99.7
LMS-AQMP2	493407, 198731	On the south-east of the site	M	Yes	Yes	4.7	1.0	25.0	0	88.0
CR-AQMP1	491291, 201143	On the Chesham Road Vent Shaft	M	Yes	Yes	4.7	1.0	27.0	0	100.0
ORC-AQMP	490503, 201786	Orchard Cottage South-eastern Site Boundary	M	Yes	Yes	5.9	2.0	41.0	0	39.9
NP-AQMP1	490069, 202008	North Portal Site Entrance	M	Yes	Yes	6.9	1.0	44.0	0	99.7


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM_{10} concentration ($\mu g/m^3$)	Minimum 1-hour PM_{10} concentration ($\mu g/m^3$)	Maximum 1-hour PM_{10} concentration ($\mu g/m^3$)	Number of 1-hour periods exceeding trigger level of 190 $\mu g/m^3$	Data capture (%)
SH-AQMP1	490152, 202395	Park Farm	M	Yes	Yes	8.8	6.9	76.6	0	99.7
SH-AQMP2	489564, 202757	King's Lane	M	Yes	Yes	2.7	0.1	48.3	0	95.8
SH-AQMP3	489569, 203654	Leather Lane	M	Yes	Yes	20.5	8.6	91.5	0	99.7
School Hill - Dust	469003, 224740	School Hill Compound	M	Yes	Yes	5.3	1.0	30.0	0	100.0
School End – Dust	463666, 230049	School End, Chetwode	M	Yes	Yes	7.8	1.0	116.0	0	100.0
Chesham Lane - Dust	487974, 205794	Chesham Lane, The Lee, Wendover	M	Yes	Yes	4.7	1.0	18.0	0	59.8
Twyford - Dust	466544, 226883	Twyford, Buckinghamshire	M	Yes	Yes	5.2	1.0	27.0	0	100.0
Chetwode/Hermitage – Dust	463936, 229521	Hermitage, Chetwode	M	Yes	Yes	6.1	1.0	40.0	0	100.0
Turweston North - Dust	460439, 237140	Turweston, Buckinghamshire	M	Yes	Yes	4.9	1.0	32.0	0	100.0
Turweston East - Dust	460556, 238280	Turweston, Buckinghamshire	M	Yes	Yes	4.1	1.0	30.0	0	62.6
FCC - Dust	469042, 224263	Adjacent Red Kite View, Calvert	M	Yes	Yes	5.3	1.0	44.0	0	100.0
Ellesborough Road - Dust	486458, 207550	Ellesborough Road, Wendover	M	Yes	Yes	5.4	1.0	28.0	0	100.0
Bacombe Lane – Dust	486528, 207217	Bacombe Lane, Wendover	M	Yes	Yes	4.6	1.0	25.0	0	99.5
Station Road – Dust	474068, 219307	Station Road, Quainton	M	Yes	Yes	4.9	1.0	23.0	0	100.0
Wendover Compound- Dust	486193, 207950	Wendover Bypass, Wendover	M	Yes	Yes	4.8	1.0	24.0	0	100.0
Woodlands - Dust	471445, 221389	Quainton, Woodlands Farmhouse	M	Yes	Yes	5.5	1.0	32.0	0	99.7


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM_{10} concentration ($\mu g/m^3$)	Minimum 1-hour PM_{10} concentration ($\mu g/m^3$)	Maximum 1-hour PM_{10} concentration ($\mu g/m^3$)	Number of 1-hour periods exceeding trigger level of 190 $\mu g/m^3$	Data capture (%)
Grove Farm	487133, 207133	Grove Farm Bungalow, Wendover	M	Yes	Yes	5.8	1.0	41.0	0	100.0
Golf Course East Ditch - Dust	479913, 213221	A418 Oxford Rd, Aylesbury	M	Yes	Yes	3.2	1.0	10.0	0	14.5
Turweston West - Dust	460204, 238084	Turweston, Buckinghamshire	M	Yes	Yes	8.0	1.0	44.0	0	33.2


Figure 7: Continuous dust 1-hour mean indicative PM_{10} concentration for all dust monitors






Hourly Mean Indicative PM10 Concentration - CHStG-AQMP2 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - LMS-AQMP1 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - LMS-AQMP1 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - CR-AQMP1 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - ORC-AQMP (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - NP-AQMP1 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - SH-AQMP1 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - SH-AQMP2 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
Average PM10 Particles (µg/m³)
PM10 Particles (µg/m³)



Hourly Mean Indicative PM10 Concentration - SH-AQMP3 (August 2026)
PM10 Concentration (µg/m³)
Measurement Time
Dust Trigger Limit
PM10 Particles (µg/m³)
Average PM10 Particles (µg/m³)



2371m - C2/C3 - EKFB - School Hill
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - School End
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Chesham Lane
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Twyford
PM10 Concentration, µgm/3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Hermitage
PM10 Concentration, µgm/3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Turweston North
PM10 Concentration, µgm/3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Turweston East
PM10 Concentration, µgm/3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - FCC
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Ellesborough Road
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Bacombe Lane
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit



2371m - C2/C3 - EKFB - Station Road
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit


2371m - C2/C3 - EKFB - Wendover Compound
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit


2371m - C2/C3 - EKFB - Woodlands
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit


2371m - C2/C3 - EKFB - Grove Farm
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit


2371m - C2/C3 - EKFB - Golf Course East Ditch
PM10 Concentration, µg/m3
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit


2371m - C2/C3 - EKFB - Turweston West
PM10 Concentration, µgm/3
200
180
160
140
120
100
80
60
40
20
0
01/08/2026 00:00
02/08/2026 00:00
03/08/2026 00:00
04/08/2026 00:00
05/08/2026 00:00
06/08/2026 00:00
07/08/2026 00:00
08/08/2026 00:00
09/08/2026 00:00
10/08/2026 00:00
11/08/2026 00:00
12/08/2026 00:00
13/08/2026 00:00
14/08/2026 00:00
15/08/2026 00:00
16/08/2026 00:00
17/08/2026 00:00
18/08/2026 00:00
19/08/2026 00:00
20/08/2026 00:00
21/08/2026 00:00
22/08/2026 00:00
23/08/2026 00:00
24/08/2026 00:00
25/08/2026 00:00
26/08/2026 00:00
27/08/2026 00:00
28/08/2026 00:00
29/08/2026 00:00
30/08/2026 00:00
31/08/2026 00:00
Measurement Time
PM10 particles (µg/m3)
Average PM10 (µg/m3)
Dust Trigger Limit