HS2

August 2026

Air Quality and Dust Monitoring Monthly Report – August 2026

London Borough of Camden

© HS2 Ltd.

Department for Transport

High Speed Two (HS2) Limited has been tasked by the Department for Transport (DfT) with managing the delivery of a new national high speed rail network. It is a non-departmental public body wholly owned by the DfT.

High Speed Two (HS2) Limited,
Two Snowhill
Snow Hill Queensway
Birmingham B4 6GA

Telephone: 08081 434 434

General email enquiries: HS2enquiries@hs2.org.uk

Website: www.gov.uk/hs2

A report prepared by EWCs and MWCCs on behalf of HS2 Ltd.

High Speed Two (HS2) Limited has actively considered the needs of blind and partially sighted people in accessing this document. The text will be made available in full on the HS2 website. The text may be freely downloaded and translated by individuals or organisations for conversion into other accessible formats. If you have other needs in this regard please contact High Speed Two (HS2) Limited.

© High Speed Two (HS2) Limited, 2026, except where otherwise stated. Copyright in the typographical arrangement rests with High Speed Two (HS2) Limited.

This information is licensed under the Open Government Licence v3.0. To view this licence, visit www.nationalarchives.gov.uk/doc/open-government-licence/ version/3 OGL or write to the Information Policy Team, The National Archives, Kew, London TW9 4DU, or e-mail: psi@nationalarchives.gsi.gov.uk. Where we have identified any third-party copyright information you will need to obtain permission from the copyright holders concerned.

recycle

Monthly Summary

1.1.1 This Summary Report is published in fulfilment of commitments detailed in the High Speed Rail (London-West Midlands) Environmental Minimum Requirements, Annex 1: Code of Construction Practice, for the nominated undertaker to present the results of air quality and dust monitoring undertaken in the London Borough of Camden (LBC) during July 2026 and August 2026 respectively.

1.1.2 Figure 1 to Figure 5 in Appendix A present the current worksites together with air quality and dust monitoring locations.

1.1.3 This summary should be read in conjunction with the overview monitoring report available from www.gov.uk/government/collections/monitoring-the-environmental-effects-of-hs2, which highlights: the applicable standards and guidance, as well as the air quality and dust monitoring methodologies to be implemented by nominated undertakers throughout construction.

1.1.4 The current worksites, as presented in Appendix A, Figure 1 to Figure 5, include:

Skanska Costain Strabag Joint Venture (SCSjv)

Adelaide Road Vent Shaft

- Works currently paused until April 2027.

Euston Scissor Cut

- Limited groundworks, concrete works and materials management.

Euston Throat Retained Cut

- Limited groundworks, concrete works and materials management.

Hampstead Road Bridge

- Utilities diversion works.

Euston Cavern

- Limited concrete, groundworks and materials management.

Mace Dragados Joint Venture (MDjv)

Main Site

- Exhumations in NR ONW area
  - Demobilise TCS from site
  - TCS cabins collected from site
  - Strip tent covers from the frame
  - Build birdcage for tent dismantle

  - Continue with tent frame dismantle
  - Geocisa – set up & start borehole drilling
  - All stockpiles being maintained

TSS works

- Continued with works to old TSS:
  - Cable Shaft 4/792: Preparations for base slab screed. Continued with enabling works for shaft capping - drilling and installation of dowel bars in preparation for the mass fill concrete pour.
  - Vent Shaft 4/791: Lifting operations (RMDs, rebar and materials).
  - JGL Yard: Steel fixers continued sorting new rebar in the order to be lifted down the vent shaft.
- Scaffolding maintenance works.
- Weekly scaffold inspections.
- TSS main yard - haul road: continued with WUR works.
- Installing concrete drainage channels (ongoing works): excavating, shuttering, adjusting manhole covers and tarmac installation works.
- Continued with installation of L wall.
- Backfilling around Pocket Park's base slabs.
- Site electrical maintenance works.
- Movement of materials.
- Old substation: collection of disused transformers.
- Various enabling works.
- Multi-service team: removing old hoarding in Drummond Street.
- Continued management of water in B3 Vent Tunnel.
- Movement of materials.
- Housekeeping.
- Hoarding alterations to Melton Street and Hammerhead walkway.
- General housekeeping (various locations).
- Removal of asset protection.
- Various carpentry works.
- Water management.

MWU West – Taxi Rank

- Non-contestable UKPN works.

Two Towers

- Continuing with intrusive survey of inverts on CX branch including cable tracing and labelling.
- Completed control point survey of Euston Station.
- I&M equipment installation of reflective prisms completed on BB and CX branch.

MF Old School

- Refurbishment work in the stairwells.

- Enabling work for link bridge and lift.
- Landscaping work to the front.

Utilities Project-wide works

- North Gower water diversion works including one night shift for flow isolation.
- Comms routes and chambers installation in TSS area.
- Comms ducting enabling works and installation at the Main Site.
- Eversholt Street secondary diversion works – saw-cutting, manual tarmac/concrete base break out, vac-ex excavation, ducting install and road reinstatement.
- MH8 Drummond Street – completed cofferdam MH8 excavation and old brick sewer de-commissioning.
- Cobourg Street – 1000mm water main piece through, commenced trench excavation.
- DM Pillar relocation at Hampstead Road.

Night shift activities at and around Euston Street

- Continuing with intrusive survey of inverts on CX branch including cable tracing and labelling.
- Completed control point survey of Euston Station.
- I&M equipment installation of reflective prisms completed on BB and CX branch.

1.1.5 Twenty-Two (22) dust monitors are installed around these worksites, where works are underway. These sites returned a medium to high dust risk rating.

1.1.6 Dust monitoring locations and results are presented in Appendix B, Table 1, together with line charts of monthly data from each dust monitor in Figure 6. All continuous dust monitoring is undertaken using indicative monitors. Despite being Environment Agency (MCERTS) certified, indicative monitors carry a higher level of uncertainty than reference monitors, and therefore cannot be strictly compared with Air Quality Standards for human health and the environment. The purpose of the monitoring undertaken is to ensure the effectiveness of the on-site mitigation.

1.1.7 The trigger level for PM_{10} concentrations of 190 µg/m^3, over a 1-hour period, in accordance with the updated guidance document '*Guidance on Monitoring in the Vicinity of Demolition and Construction Sites – (October 2018)*' has been applied.

1.1.8 No (0) dust trigger alerts were recorded during the monitoring period (August 2026).

1.1.9 Data capture was below 90% at multiple monitors. AQ054 and AQ011 were due to power supply issues, while AQ008 and AQ020 experienced reduced capture due to ongoing airflow faults; AQ008 and AQ020 were subsequently replaced with repaired monitors on 25/08/2026 and 17/08/2026, respectively, after which concentrations returned to typical levels, with all other monitored results remaining within expected ranges.

1.1.10 Diffusion tube monitoring of Nitrogen Dioxide (NO_2) is undertaken at sixty-four (64) locations around highways within the LBC as part of the management of air quality where significant effects may occur as a result of the scheme.


1.1.11 Diffusion tube monitoring results are as provided from the laboratory analysis, and therefore still require various analysis and adjustments to be undertaken. Final corrected results will be presented and described in the annual report. However, based on the results to date, no unexpected values were recorded during the monitoring period.

1.1.12 NO_2 monitoring locations and results are presented in Appendix C, Table 2, together with the 2026 running mean.

1.1.13 There were no (0) complaints received during the reporting period (August 2026).

Appendix A – Worksites and Monitoring Locations

Figure 1 to Figure 5: Worksites and monitoring locations within the LBC



Legend

- Diffusion Tube
- District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Monitoring Locations In LBC (Sheet 1)

London Borough of Camden

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.


© Crown copyright and database rights 2022. Ordnance Survey Licence Number 100049190.

Scale at A3: 1:10,000

0 100 200 300 400 Metres

Doc Number:

Date: 25/10/22



Legend

- Diffusion Tube
- Worksite
- Dust Monitor
- District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Worksite and Monitoring Locations In LBC (Sheet 2)

London Borough of Camden

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.


© Crown copyright and database rights 2022. Ordnance Survey Licence Number 100049190.

Scale at A3: 1:7,000

0 70 140 210 280 Metres

Doc Number:

Date: 25/10/22



Legend

Dust Monitor
District Borough Unitary Boundaries
Worksite

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Worksite & Monitoring Locations In LBC (Sheet 3)

London Borough of Camden

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.


© Crown copyright and database rights 2023. Ordnance Survey Licence Number 100049190.

Scale at A3: 1:7,000

0 70 140 210 280
Metres

Doc Number:

Date: 18/05/23



Legend

Diffusion Tube | District Borough Unitary Boundaries

Worksite

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Worksite & Monitoring Locations In LBC (Sheet 4)

London Borough of Camden

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686. Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.


© Crown copyright and database rights 2023. Ordnance Survey Licence Number 100049190.

Scale at A3: 1:7,000

0 70 140 210 280 Metres

Doc Number:

Date: 18/05/23



Legend

- Diffusion Tube
- District Borough Unitary Boundaries

Service Layer Credits: Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey, Esri Japan, METI, Esri China (Hong Kong), (c) OpenStreetMap contributors, and the GIS User Community

Map Number

Map Name

Worksite and Monitoring Locations In LBC (Sheet 5)

London Borough of Camden

HS2 Ltd accept no responsibility for any circumstances, which arise from the reproduction of this map after alteration, amendment or abbreviation or if it is issued in part or issued incomplete in any way.

Registered in England. Registration number 06791686.
Registered office: 2 Snowhill, Queensway, Birmingham B4 6GA.

© Crown copyright and database rights 2022. Ordnance Survey Licence Number 100049190.

Scale at A3: 1:4,000

0 40 80 120 160 Metres

Doc Number:

Date: 25/10/22

Appendix B – Dust Monitoring Results


Table 1: Dust Monitoring Locations and Results

Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM_{10} concentration ($\mu g/m^3$)	Minimum 1-hour PM_{10} concentration ($\mu g/m^3$)	Maximum 1-hour PM_{10} concentration ($\mu g/m^3$)	Number of 1- hour periods exceeding trigger level of 190 $\mu g/m^3$	Data capture (%)
AQ001	529016, 183049	Junction of Park Village East, Stanhope Street and Granby Terrace	M	Yes	N	7.1	4.1	25.8	0	100.0
AQ002	528924, 183130	Park Village East	M	Yes	N	7.4	5.0	27.5	0	100.0
AQ003	529273, 182698	St James' Gardens	M	Yes	N/A	8.7	1.6	58.8	0	100.0
AQ004	529533, 182519	Melton Street	H	Yes	N/A	8.1	0.5	117.0	0	100.0
AQ005	529498, 182502	Stephenson Way	H	Yes	N/A	18.6	4.3	122.1	0	100.0
AQ006	529388, 182524	Euston Street	H	Yes	N/A	6.3	0.6	31.0	0	100.0
AQ007	529361, 182574	Drummond Street	H	Yes	N/A	26.2	7.1	126.0	0	100.0
AQ008	529372, 182657	Cobourg Street	H	Yes	N/A	29.5	6.5	88.6	0	20.4
AQ009	529707, 182730	Eversholt Street	H	Yes	N/A	20.9	5.6	75.8	0	100.0
AQ010	529223, 182746	Hampstead Road South	M	Yes	N/A	22.0	6.0	134.6	0	100.0
AQ011	529176, 182922	Hampstead Road	M	Yes	N	6.9	5.0	25.0	0	88.0


Monitoring site ID	Coordinates (X,Y)	Location description	Dust risk rating for site	Monitoring site active during period	Change to site since previous period report	Mean 1-hour PM_{10} concentration ($\mu g/m^3$)	Minimum 1-hour PM_{10} concentration ($\mu g/m^3$)	Maximum 1-hour PM_{10} concentration ($\mu g/m^3$)	Number of 1- hour periods exceeding trigger level of 190 $\mu g/m^3$	Data capture (%)
AQ012	529144, 182941	Rear of Coniston House	M	Yes	N	7.1	4.0	25.3	0	99.1
AQ013	529066, 182990	Regents Park Estate	M	Yes	N	7.6	4.5	26.5	0	99.6
AQ016	528820, 183498	Mornington Terrace North	M	Yes	N	7.5	5.0	26.0	0	99.9
AQ017	528962, 183274	Mornington Terrace South	M	Yes	N	7.2	4.7	25.0	0	99.6
AQ018	529192, 183071	Hampstead Road North	M	Yes	N	7.3	4.1	27.5	0	99.6
AQ019	528689, 183500	Park Village East (North)	M	Yes	N	7.4	4.8	27.8	0	99.9
AQ020	529109, 182605	Netley School	n/a	Yes	N/A	10.5	3.1	58.4	0	59.7
AQ021	529136, 183086	Site compound at the Junction of Hampstead Road & Granby Terrace Bridge	M	Yes	N	7.1	4.1	25.0	0	99.2
AQ044	527725, 184369	Adelaide Road 1	M	Yes	N	7.2	4.8	26.3	0	99.1
AQ045	527826, 184375	Adelaide Road 2	M	Yes	N	7.2	5.0	25.0	0	99.2
AQ054	529266, 183076	Ampthill Estate, Hampstead Road	M	Yes	N	7.6	0.2	28.1	0.0	44.2

Figure 6: Construction dust 1-hour mean indicative PM_{10} concentration for all dust monitors


AQ001




AQ002




AQ003




AQ004




AQ005




AQ006




AQ007




AQ008




AQ009




AQ010




AQ011




AQ012




AQ013




AQ016




AQ017




AQ018




AQ019




AQ020




AQ021




AQ044



AQ045


350.0
300.0
250.0
200.0
150.0
100.0
50.0
0.0
PM10 particles (ug/m³)
01/08/2026
06/08/2026
11/08/2026
16/08/2026
21/08/2026
26/08/2026
31/08/2026
PM10 particles (ug/m³)
Average
Alarm - 190 ug/m³

AQ054


350.0
300.0
250.0
200.0
150.0
100.0
50.0
-
PM10 particles (ug/m³)
01/08/2026
06/08/2026
11/08/2026
16/08/2026
21/08/2026
26/08/2026
31/08/2026
PM10 particles (ug/m³)
Average
Alarm - 190 ug/m³

Appendix C – Air Quality Monitoring Results

Table 2: NO_2 monitoring locations around highways, NO_2 concentrations and monthly monitoring results with running mean for 2026 (µg/m^3)

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[1][2]
HS2-000020BM5	Junction of St Chad's Street and Grays Inn Road	530436, 182929	40	38	21	31	35	29	27						31
HS2-000020BM7	Chalton Street	529894, 182702	46	43	38	28	51	50	19						39
HS2-000020BM8	Junction of Euston Square and Grafton Place	529737, 182641	48	48	39	36	38	32	31						39
HS2-000020BM9	Junction of Endsleigh Gardens and Upper Woburn Place	529785, 182529	44	39	40	33	33	25	30						35
HS2-000020BMA	Junction of Euston Road and Gower Street	529429, 182375	46	43	38	31	35	32	29						36
HS2-000020BMB	Whitfield Street	529273, 182114	39	34	32	28	25	19	16						28
HS2-000020BMC	Hampstead Road	529232, 182511	29	52	46	42	43	39	31						40
HS2-000020BMF	Junction of Polygon Road and Ossulston Street	529715, 183123	43	35	28	16	18	16	14						24

[1] *Note: to aid interpretation and conform with best practice, the monthly measurements in this table are reported rounded to the nearest whole number. The annual mean presented here is calculated based on laboratory data to 4 significant figures, rounded to a whole number, and therefore may differ slightly to a mean derived from averaging the rounded monthly measurements in the table.*

[2] *The annual mean for diffusion tubes presented in the table above still require various analysis and adjustments to be undertaken before comparison to the Air Quality Objectives. The final corrected annual mean will be presented in the HS2 Annual Air Quality Report.*

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[12]
HS2-000020BMH	Nash Street	528861, 182717	34	27	24	18	21	18	14						22
HS2-000020BMJ	Junction on Robert Street and Stanhope Street	529080, 182698	37	21	25	22	22	17	Tube Missing						24
HS2-000020BMK	Junction of Plender Street and Bayham Street	529196, 183546	39	38	32	29	32	24	22						31
HS2-000020BML	Junction of Arlington Road and Mornington Crescent	529093, 183356	36	26	28	22	20	16	14						23
HS2-000020BMM	Junction of Bayham Street and Pratt Street	529084, 183722	42	36	41	30	23	31	28						33
HS2-000020BMN	Junction of Delancey Street and Albert Street	528850, 183573	Tube Missing	23	30	25	26	25	20						25
HS2-000020BMQ	Junction of Parkway and Delancey Street	528662, 183604	39	35	30	24	22	26	Tube Missing						29
HS2-000020BMR	Junction of Oval Road and Jamestown Road	528548, 183967	24	26	29	24	20	17	16						22
HS2-000020BMS	Junction of Chalk Farm Road and Castlehaven Road	528685, 184188	42	31	30	28	30	24	23						30
HS2-000020BMT	Junction of Camden Road and Camden Street	529079, 184043	41	34	34	29	28	24	26						31
HS2-000020BMU	Junction of Southampton Road and Fleet Road	527783, 185407	37	29	30	25	22	33	12						27

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[12]
HS2-000020BMV	Primrose Hill Road	527538, 184250	Tube Missing	25	22	13	15	16	Tube Missing						18
HS2-000020BMW	Junction of Finchley Road and Hilgrove Road	526619, 184081	42	37	24	31	32	42	15						32
HS2-000020BMZ	Junction of Finchley Road and Hendon Way	525102, 186042	53	39	46	45	34	37	22						40
HS2-000020BNA	Junction of Regent's Park Road and Rothwell Street	527884, 183980	Tube Missing	36	23	Tube Missing	18	24	8						22
HS2-000020BNC	Junction of Outer Circle and Gloucester Gate	528528, 183443	30	21	21	16	16	13	13						18
HS2-000020BNH	Junction of Parkway and Albert Street	528763, 183720	Tube Missing	29	Tube Missing	16	10	20	18						18
HS2-000020BNN	Lincoln's Inn Fields	530744, 181308	34	31	27	22	22	21	Tube Missing						26
HS2-000020BNQ	Camley Street	529735, 183737	38	33	32	Tube Missing	Result Removed	20	Tube Missing						25
HS2-000020BNY	Junction of Mill Lane and Hillfield Road	524839, 185136	28	21	28	19	19	25	9						21
HS2-000020BNZ	Mansfield Road	528050, 185508	Tube Missing	27	25	14	17	24	8						19
HS2-000020BP0	Junction of Camden Road and Torriano Avenue	529708, 184871	31	31	33	27	29	41	14						30
HS2-000020BP2	Junction of Grays Inn Road and Holborn	531149, 181616	36	32	29	23	25	22	19						26

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[12]
HS2-000020BPB	Camden High Street	528966, 183735	49	45	43	37	36	34	30						39
HS2-000020BPC	Castlehaven Road	528788, 184591	34	33	27	18	18	23	8						23
HS2-000020BPD	Prince of Wales Road	528571, 184683	25	28	22	18	14	19	6						19
HS2-000020BPE	Haverstock Hill	527710, 184749	33	30	28	17	18	27	7						23
HS2-000020BPF	Junction of Primrose Gardens and England's Lane	527549, 184640	34	29	26	20	14	22	8						22
HS2-000020BPU	Junction of Gower Street and Grafton Way	529476, 182267	46	39	34	31	30	25	20						32
HS2-000020BPW	Junction of Delancey Street and Arlington Road	528939, 183637	40	33	33	25	21	23	21						28
HS2-000020BPX	Netley Street	529177, 182625	36	28	28	22	19	19	16						24
HS2-000020BPY	Stanhope Street	529060, 182947	32	26	25	18	16	13	12						20
HS2-000020BPZ	Albany Street	528790, 182923	24	28	27	21	20	19	17						22
HS2-000020BQ0	Werrington Street	529493, 183113	35	27	22	19	Tube Missing	14	13						22
HS2-000020BQ1	Polygon Road	529574, 183045	Tube Missing	26	27	19	20	15	13						20
HS2-000020BQ2	Alexandra Place	526320, 183980	29	27	22	16	18	23	7						20
HS2-000020BQ3	Harrington Square	529228, 183172	38	31	30	26	24	21	20						27
HS2-000020BQ4	Junction of North Gower Street and Starcross Street	529290, 182572	38	28	26	22	20	17	15						24

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[12]
HS2-000020BQ5	Adelaide Road	527713, 184392	32	28	27	19	17	25	7						22
HS2-000020BQ6	Mornington Terrace	528836, 183474	29	24	21	16	16	13	12						19
HS2-000020BQ7	Arlington Road	529009, 183479	32	23	24	16	17	14	12						20
HS2-000020BQ8	Clarkson Row	529024, 183213	33	23	25	17	17	13	12						20
HS2-000020BQ9	Park Village East	528923, 183121	29	Tube Missing	23	19	16	15	12						19
HS2-000020BQA	Eversholt Street	529386, 183132	39	36	37	29	26	24	21						30
HS2-000020BQB	Junction of Harrington Street and Varndell Street	529147, 182816	35	26	26	19	17	13	11						21
HS2-000020BQC	Junction of Robert Street and Hampstead Road	529199, 182704	49	37	31	28	28	20	18						30
HS2-000020BQD	Drummond Crescent	529648, 182856	35	29	27	26	21	17	16						24
HS2-000020BQJ	Grafton Way	529380, 182225	37	Tube Missing	35	29	30	28	23						30
HS2-000020BQL	Delancey Street	528768, 183581	39	31	37	28	28	21	25						30
HS2-000020BQR	Lamp post on Park Village East	528682, 183505	30	24	25	17	Tube Missing	Tube Missing	Tube Missing						24
HS2-000020BQS	Opposite Maria fidelis school on Phoenix Road	529670, 182982	35	27	20	20	18	15	8						20
HS2-000020BQT	Drummond Street	529385, 182581	40	31	26	23	23	19	16						25
HS2-000020BQX	Lamp post on Brunswick Square	530344, 182236	40	34	31	22	16	21	16						26

Monitoring Site ID	Location description	Coordinates (X, Y)	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Mean[12]
HS2-000020BP4	Triplicate site on Finchley Road next to Swiss Cottage kerbside automatic monitoring station	526633, 184392	40	37	34	28	27	Tube Missing	13						30
HS2-000020BP5	Triplicate site next to the Euston Road roadside automatic monitoring stations	529895, 182657	52	50	48	49	50	41	39						47
HS2-000020BP9	Triplicate site in Russell Square next to Bloomsbury urban background automatic monitoring station	530120, 182034	33	29	28	23	21	16	19						24